

To: Rodriguez, Dante[Rodriguez.Dante@epa.gov]; Seter, David[Seter.David@epa.gov]; chairman@wrpt.us[chairman@wrpt.us]; amber torres[freebella123@yahoo.com]; Swann, Veronica[Swann.Veronica@epa.gov]
Cc: kalland@usgs.gov[kalland@usgs.gov]; Carl Thodal[cethodal@usgs.gov]; rthomas@blm.gov[rthomas@blm.gov]
From: Cynthia Oceguela
Sent: Thur 8/25/2016 2:00:34 AM
Subject: Wabuska drain
[20160824_153011.jpg](#)

Hello everyone,

This picture was taken today as I toured Walker River with Veronica, giving her a face to face with the wastewater spill area and found a new ditch.

Since our Internet is not working, I will be communicating through gmail.

I am very concerned about what I saw which I consider the aftermath of the January spill.

I'm not sure who the responsible party is for digging the ditch from the drain area, but what is there happens to flow into the walker river.

Our first step should be to determine who is doing this.

We then need to check the quality of the water and capture soil sediment samples. The vegetation is damaged, the smell is very difficult to contend with, and the piled up soil is hardened and gray from the burned water that was in that area.

I recommend follow up as soon as we can arrange it.

I do not want to wait four months to learn more.

Thanks everyone,

Cynthia Oceguela